



**Star
Home
Inspection Services**

Home Inspection Report

12081 S Troost St Olathe, KS 66061

Inspection Date: 02/12/2010

Prepared For: Ami Swisher

Prepared By: Star Home Inspection Services LLC
705B SE Melody Lane, Suite 124
Lee's Summit, MO 64063
(816) 554-1110
(816) 554-2135 Fax

Report Number: 02122010-2A

Inspector: Alan DeMoss



Table Of Contents

REPORT OVERVIEW	3
STRUCTURE	7
ROOFING	9
EXTERIOR	10
ELECTRICAL	12
HEATING	13
COOLING / HEAT PUMPS	14
INSULATION / VENTILATION	15
PLUMBING	16
INTERIOR	17
APPLIANCES	19
FIREPLACES / WOOD STOVES	20

Report Overview

THE HOUSE IN PERSPECTIVE

This is an average quality home. As with all homes, ongoing maintenance is required and improvements to the systems of the home will be needed over time. *The improvements that are recommended in this report are not considered unusual for a home of this age and location.* Please remember that there is no such thing as a perfect home.

CONVENTIONS USED IN THIS REPORT

For your convenience, the following conventions have been used in this report.

Major Concern: a system or component which is considered significantly deficient or is unsafe. Significant deficiencies need to be corrected and, except for some safety items, are likely to involve significant expense.

Safety Issue: denotes a condition that is unsafe and in need of prompt attention.

Repair: denotes a system or component which is missing or which needs corrective action to assure proper and reliable function.

Improve: denotes improvements which are recommended but not required.

Monitor: denotes a system or component needing further investigation and/or monitoring in order to determine if repairs are necessary.

Please note that those observations listed under “Discretionary Improvements” are not essential repairs, but represent logical long term improvements.

- For the purpose of this report, it is assumed that the house faces north.

IMPROVEMENT RECOMMENDATION HIGHLIGHTS / SUMMARY

The following is a synopsis of the potentially significant improvements that should be budgeted for over the short term. Other significant improvements, outside the scope of this inspection, may also be necessary. Please refer to the body of this report for further details on these and other recommendations.

All issues found in this report should be addressed with the appropriate parties to make any improvements, corrections or repairs necessary. All improvements, corrections and repairs should meet the satisfaction of the client named on this report and the inspection agreement associated with this report prior to closing. This report and the findings listed herein are intended for the client only and is not transferable without a signed written agreement.

Seller comments are in red. Any items without seller comments should be considered “as is”

Foundation

- **Monitor:** The basement floor slab has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Roof

- **Monitor:** No roof sheathing clips were observed between the sheathing panels. This condition is fairly common and not unusual, although it is recommend this be investigated further when re-roofing
- **Repair:** Evidence of moisture was observed on the underside of the roof sheathing near the chimney siding. This can weaken the sheathing and ultimately necessitate replacement. Roof/Chimney flashing repairs were in progress at the time of inspection. **Repaired 2/13/10**
- **Monitor:** Construction mold was visible on some roof rafters. This is mold that grows on the lumber while lying in the weather during construction as evidenced by the strap marks. Most homes have some level of this mold and it goes dormant once removed from the elements and normally does not present any problems.

Flashings

- **Monitor:** The skylight flashing should be carefully monitored. Skylight flashings are extremely vulnerable to leakage.
- **Repair:** The chimney flashing leaks, repairs are needed. Renovations were in progress at the time of inspection. **Repaired 2/13/10**
- **Monitor, Repair:** The plumbing vent flashing boot(s) is split making it vulnerable to leaks. It's recommended that the boot be caulked or the flashing replaced. **Repaired (caulked) 2/13/10**

Exterior Walls

- **Repair:** The exterior siding paint is peeling and/or worn thin in localized areas (i.e. near kitchen window and at bottom edge on east side of home). These areas should be painted to prevent water damage or rot in the future. **Repaired 2/13/10**
- **Monitor:** Siding of this type requires monitoring and maintenance. It has a tendency to pop out past nail heads creating a space where two panels join together. Re-securing and caulking the seams and nail holes is standard maintenance for this type of siding.
- **Repair:** The siding trim needs caulking improvements in localized areas to prevent water damage and rot. **Repaired 2/13/10**
- **Repair:** Localized rot/damage was observed in the trim around the siding (i.e. at southeast corner, near overhead door and at front porch rail trim). Following repair of the damaged areas (which should be combined with exterior painting/maintenance) proper maintenance of the siding and control of water from roof or surface runoff can avoid further damage. Renovations were in progress at the time of inspection. **Repaired 2/13/10**

Windows

- **Repair:** Some of the windows require caulking.

Doors

- **Repair:** The slider door frame/ trim requires caulking. **Repaired 2/13/10**

Garage

- **Monitor:** The garage floor slab has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Lot Drainage

- **Monitor:** The grading should be maintained to promote the flow of storm water away from the house. This can often be accomplished by the addition of top soil. The ground should slope away from the house at a rate of one inch per foot for at least the first five feet. At least eight (8) inches of clearance should be maintained between soil level and the bottom of exterior wall siding. ***It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future. If another rain occurs before closing, it's recommended the basement be viewed again for any signs of moisture penetration.***

Driveway

- **Monitor:** The driveway has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Landscaping

- **Repair:** Shrubs, bushes and/or vines growing on exterior walls need to be trimmed away from the structure to reduce the risk of water damage and insect infestation. **Will repair before closing**

Central Air Conditioning

- **Monitor:** The fins of the outdoor portion of the air conditioning system were observed to be damaged. This condition can reduce the efficiency of the system.

Attic / Roof

- **Monitor:** While in the attic water stains were observed on the lower sections of the furnace flue. The insulation below the elbow also showed signs of past moisture. It appears that rain blew in under the rain cap and came down the interior of the flue until it got to the first joint where it then transferred to the outside surface and dripped off the elbow. This is a common condition in 80% of homes but very seldom is enough to penetrate completely through the insulation to the drywall below. Monitor for any additional wetness after rains.

Water Heater

- **Monitor:** Water heaters have a typical life expectancy of 7 to 12 years. The existing unit is approaching or has exceeded this age range. One cannot predict with certainty when replacement will become necessary.

Plumbing Fixtures

- **Improve:** Cracked, deteriorated and/or missing master shower stall caulk should be replaced.
- **Improve:** Cracked, deteriorated and/or missing hall bath and master bath bathtub enclosure caulk could be improved.
- **Improve:** Cracked, deteriorated and/or missing master bath sink side splash caulk should be replaced.

Caulk has been repaired in Master bath and Hall Bath.

Caulk will be repaired in Master bath shower and sink side splash before closing.

Wall / Ceiling Finishes

- **Monitor:** Water staining was noted at the basement ceiling.
- **Monitor:** Repaired drywall damage was noted (i.e. upper hall bath and master bath). Renovations were in progress at the time of the inspection.
- **Monitor:** Typical drywall flaws were observed that could include minor cracks, rough seams, nail popping, minor patching, etc. Any repairs would be discretionary. Overall condition is above average.

Floors

- **Monitor:** The vinyl flooring in the laundry room was observed to have minor stain.
- **Monitor:** The carpet shows typical wear and/or minor soiled spots and stains.

Windows

- **Monitor, Repair:** The interior window sills in the master bedroom are peeling. Repair is discretionary. **Repaired (sanded and painted) 2/14/10**

Doors

- **Repair:** Doors should be trimmed or adjusted as necessary to work properly (i.e. master bath door). **Repaired 2/13/10**
- **Repair:** The threshold at the garage man door is damaged. Repair is needed.

Basement Leakage

- **Monitor:** No evidence of moisture penetration was visible in the basement at the time of the inspection. ***It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future.*** The vast majority of basement leakage problems are the result of insufficient control of storm water at the surface. The ground around the house should be sloped to encourage water to flow away from the foundation. Gutters and downspouts should act to collect roof water and drain the water at least five (5) feet from the foundation or into a functional storm sewer. Downspouts that are clogged or broken below grade level, or that discharge too close to the foundation are the most common source of basement leakage. Please refer to the Roofing and Exterior sections of the report for more information.

In the event that basement leakage problems are experienced, lot and roof drainage improvements should be undertaken as a first step. Please beware of contractors who recommend expensive solutions. Excavation, damp-proofing and/or the installation of drainage tiles should be a last resort. In some cases, however, it is necessary. Your plans for using the basement may also influence the approach taken to curing any dampness that is experienced. If another rain occurs before closing, it's recommended the basement be viewed again for any signs of moisture penetration.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI® Standards of Practice are inspected, except as may be noted in the “Limitations of Inspection” sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind.

This inspection is visual only. A representative sample of building components are viewed in areas that are accessible at the time of the inspection. No destructive testing or dismantling of building components is performed.

Please refer to the pre-inspection contract for a full explanation of the scope of the inspection.

WEATHER CONDITIONS

There was snow on the ground during the course of the inspection.

The estimated outside temperature was 36 degrees F.

RECENT WEATHER CONDITIONS

Winter weather conditions have been experienced in the days leading up to the inspection.

Structure

DESCRIPTION OF STRUCTURE

Foundation:	•Poured Concrete •Basement Configuration •65% Of Foundation Was Not Visible From Inside Due To Finished Walls and/or Storage
Columns:	•Steel
Floor Structure:	•Wood Joist •Concrete
Wall Structure:	•Wood Frame
Ceiling Structure:	•Joist
Roof Structure:	•Rafters •Waferboard Sheathing

STRUCTURE OBSERVATIONS

Positive Attributes

The construction of the home is good quality. The materials and workmanship, where visible, are good. The visible joist spans appear to be within typical construction practices. The inspection did not discover evidence of substantial structural movement.

General Comments

No major defects were observed in the accessible structural components of the house.

RECOMMENDATIONS / OBSERVATIONS

Foundation

- **Monitor:** The basement floor slab has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Roof

- **Monitor:** No roof sheathing clips were observed between the sheathing panels. This condition is fairly common and not unusual, although it is recommend this be investigated further when re-roofing
- **Repair:** Evidence of moisture was observed on the underside of the roof sheathing near the chimney siding. This can weaken the sheathing and ultimately necessitate replacement. Roof/Chimney flashing repairs were in progress at the time of inspection. **Repaired 2/13/10**



- **Monitor:** Construction mold was visible on some roof rafters. This is mold that grows on the lumber while lying in the weather during construction as evidenced by the strap marks. Most homes have some level of this mold and it goes dormant once removed from the elements and normally does not present any problems.



LIMITATIONS OF STRUCTURE INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Structural components concealed behind finished surfaces could not be inspected.
- Only a representative sampling of visible structural components were inspected.
- Furniture and/or storage restricted access to some structural components.
- Engineering or architectural services such as calculation of structural capacities, adequacy, or integrity are not part of a home inspection.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Roofing

DESCRIPTION OF ROOFING

Roof Covering:	•Asphalt Shingle
Roof Flashings:	•Metal •Roofing Material (Shingles)
Chimneys:	•Metal below siding
Roof Drainage System:	•Aluminum •Downspouts discharge above grade
Skylights:	•Curb-Type
Method of Inspection:	•Walked on roof •Viewed from ladder at eave •Viewed with binoculars •Viewed from window

ROOFING OBSERVATIONS

Positive Attributes

The roof coverings are to be in generally good condition. Where investigated, eave protection has been installed below the sloped roof coverings. This reduces the risk of roof leakage, should ice damming develop in the winter. The gutters are clean.

RECOMMENDATIONS / OBSERVATIONS

Flashings

- **Monitor:** The skylight flashing should be carefully monitored. Skylight flashings are extremely vulnerable to leakage.
- **Repair:** The chimney flashing leaks, repairs are needed. Renovations were in progress at the time of inspection. **Repaired 2/13/10**
- **Monitor, Repair:** The plumbing vent flashing boot(s) is split making it vulnerable to leaks. It's recommended that the boot be caulked or the flashing replaced. **Repaired (caulked) 2/13/10**

LIMITATIONS OF ROOFING INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Not all of the underside of the roof sheathing is inspected for evidence of leaks.
- Evidence of prior leaks may be disguised by interior finishes.
- Estimates of remaining roof life are approximations only and do not preclude the possibility of leakage. Leakage can develop at any time and may depend on rain intensity, wind direction, ice build up, and other factors.
- Antennae, chimney/flue interiors which are not readily accessible are not inspected and could require repair.
- Roof inspection may be limited by access, condition, weather, or other safety concerns.
- Portions of the roof were viewed from the ground using binoculars. Some sections of the roof could not be viewed.
- Portions of the roof were viewed from a ladder at the edge of the roof. Some sections of the roof were not in view.
- A chimney was not entirely visible during the inspection of the roofing system.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Exterior

DESCRIPTION OF EXTERIOR

Wall Covering:	•Hardboard
Eaves, Soffits, And Fascias:	•Wood
Exterior Doors:	•Metal •Sliding Glass
Window/Door Frames and Trim:	•Vinyl-Covered
Entry Driveways:	•Concrete
Entry Walkways And Patios:	•Concrete •Pavers
Porches, Decks, Steps, Railings:	•Concrete •Wood
Overhead Garage Door(s):	•Wood •Automatic Opener Installed
Surface Drainage:	•Level Grade •Graded Away From House
Retaining Walls:	•Prefab Masonry
Fencing:	•None

EXTERIOR OBSERVATIONS

Positive Attributes

Window frames are clad, for the most part, with a low maintenance material. The wood window frames are in generally good condition. The auto reverse mechanism on the overhead garage door responded properly to testing. This safety feature should be tested regularly as a door that doesn't reverse can injure someone or fall from the ceiling. Refer to the owner's manual or contact the manufacturer for more information. The driveway and walkways are in good condition. The garage completely finished. Freeze resistant hose bibs (exterior faucets) have been installed.

General Comments

The exterior of the home is generally in good condition.

RECOMMENDATIONS / OBSERVATIONS

Exterior Walls

- **Repair:** The exterior siding paint is peeling and/or worn thin in localized areas (i.e. near kitchen window and at bottom edge on east side of home). These areas should be painted to prevent water damage/rot in the future. **Repaired 2/13/10**
- **Monitor:** Siding of this type requires monitoring and maintenance. It has a tendency to pop out past nail heads creating a space where two panels join together. Re-securing and caulking the seams and nail holes is standard maintenance for this type of siding.
- **Repair:** The siding trim needs caulking improvements in localized areas to prevent water damage and rot. **Repaired 2/13/10**
- **Repair:** Localized rot/damage was observed in the trim around the siding (i.e. at southeast corner, near overhead door and at front porch rail trim). Following repair of the damaged areas (which should be combined with exterior painting/maintenance) proper maintenance of the siding and control of water from roof or surface runoff can avoid further damage. Renovations were in progress at the time of inspection. **Repaired 2/13/10**



Windows

- **Repair:** Some of the windows require caulking. **Repaired 2/13/10**

Doors

- **Repair:** The slider door frame/ trim requires caulking. **Repaired 2/13/10**

Garage

- **Monitor:** The garage floor slab has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Lot Drainage

- **Monitor:** The grading should be maintained to promote the flow of storm water away from the house. This can often be accomplished by the addition of top soil. The ground should slope away from the house at a rate of one inch per foot for at least the first five feet. At least eight (8) inches of clearance should be maintained between soil level and the bottom of exterior wall siding. ***It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future. If another rain occurs before closing, it's recommended the basement be viewed again for any signs of moisture penetration.***

Driveway

- **Monitor:** The driveway has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Landscaping

- **Repair:** Shrubs, bushes and/or vines growing on exterior walls need to be trimmed away from the structure to reduce the risk of water damage and insect infestation. **Will repair before closing**

LIMITATIONS OF EXTERIOR INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- A representative sample of exterior components was inspected rather than every occurrence of components.
- The inspection does not include an assessment of geological, geotechnical, or hydrological conditions, or environmental hazards.
- Screening, shutters, awnings, or similar seasonal accessories, fences, recreational facilities, outbuildings, seawalls, break-walls, docks, erosion control and earth stabilization measures are not inspected unless specifically agreed-upon and documented in this report.
- Storage in the garage restricted the inspection.
- Snow restricted an inspection of the lot and various other aspects of the exterior of the house.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Electrical

DESCRIPTION OF ELECTRICAL

Size of Electrical Service:	•120/240 Volt Main Service - Service Size: 200 Amps
Service Drop:	•Underground
Service Entrance Conductors:	•Aluminum
Service Equipment & Main Disconnects:	•Main Service Rating 200 Amps •Breakers •Located: Basement
Service Grounding:	•Copper •Water Pipe Connection
Service Panel & Overcurrent Protection:	•Panel Rating: 200 Amp •Breakers •Located: Basement
Sub-Panel(s):	•None Visible
Distribution Wiring:	•Copper
Wiring Method:	• Non-Metallic Cable "Romex"
Switches & Receptacles:	•Grounded
Ground Fault Circuit Interrupters:	•Bathroom(s) •Exterior •Garage •Kitchen •Basement
Smoke Detectors:	•Present

ELECTRICAL OBSERVATIONS

Positive Attributes

The size of the electrical service is sufficient for typical single family needs. The electrical panel is well arranged and all fuses/breakers are properly sized relative to the wiring. Generally speaking, the electrical system is in good order. All outlets and light fixtures that were tested operated satisfactorily. The distribution of electricity within the home is good. All 3-prong outlets that were tested were appropriately grounded. Ground fault circuit interrupter (GFCI) devices have been provided in some areas of the home. These devices are extremely valuable, as they offer an extra level of shock protection. All GFCI's that were tested responded properly unless otherwise noted below. Dedicated 220 volt circuits have been provided for all 220 volt appliances within the home. All visible wiring within the home is copper. This is a good quality electrical conductor.

General Comments

Inspection of the electrical system revealed the need for typical, minor repairs. Although these are not costly to repair, they should be high priority for safety reasons. ***Unsafe electrical conditions represent a shock hazard.*** A licensed electrician should be consulted to undertake the repairs recommended below.

RECOMMENDATIONS / OBSERVATIONS

LIMITATIONS OF ELECTRICAL INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Electrical components concealed behind finished surfaces are not inspected.
- Only a representative sampling of outlets and light fixtures were tested.
- Furniture and/or storage restricted access to some electrical components which may not be inspected.
- The inspection does not include remote control devices, alarm systems and components, low voltage wiring, systems, and components, ancillary wiring, systems, and other components which are not part of the primary electrical power distribution system.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Heating

DESCRIPTION OF HEATING

Energy Source:	•Gas
Heating System Type:	•Forced Air Furnace •Manufacturer: Lennox •Serial Number: 5899J 50664
Vents, Flues, Chimneys:	•Metal-Single Wall
Heat Distribution Methods:	•Ductwork
Other Components:	•Humidifier

HEATING OBSERVATIONS

Positive Attributes

Heating a home with a this type of heating system should be relatively economical. Adequate heating capacity is provided by the system. Heat distribution within the home is adequate. The heating system is controlled by a “set back” thermostat. This type of thermostat, if set up correctly, helps reduce heating costs.

General Comments

The heating system shows no visible evidence of major defects.

RECOMMENDATIONS / OBSERVATIONS

LIMITATIONS OF HEATING INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- The adequacy of heat supply or distribution balance is not inspected.
- The interior of flues or chimneys which are not readily accessible are not inspected.
- The furnace heat exchanger, humidifier, or dehumidifier, and electronic air filters are not inspected.
- Solar space heating equipment/systems are not inspected.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Cooling / Heat Pumps

DESCRIPTION OF COOLING / HEAT PUMPS

Energy Source:	•Electricity
Central System Type:	•Air Cooled Central Air Conditioning •Manufacturer: Lennox
	•Serial Number: 5800B 37461
Size of Circuit:	•Circuit Size: Minimum Circuit Size 21.5 Amps Maximum Circuit Breaker Size 35 Amps
	•Breaker Size In Main Panel: 30 Amps
Other Components:	•House Fan

COOLING / HEAT PUMPS OBSERVATIONS

Positive Attributes

The capacity and configuration of the system should be sufficient for the home. The location of the return air vents is well suited to air conditioning.

General Comments

As the system is a middle aged unit a higher level of maintenance can be expected.

RECOMMENDATIONS / OBSERVATIONS

Central Air Conditioning

- **Monitor:** The fins of the outdoor portion of the air conditioning system were observed to be damaged. This condition can reduce the efficiency of the system.

LIMITATIONS OF COOLING / HEAT PUMPS INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Window mounted air conditioning units are not inspected.
- The cooling supply adequacy or distribution balance are not inspected.
- **The air conditioning system could not be tested as the outdoor temperature was below 60 degrees F.**

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Insulation / Ventilation

DESCRIPTION OF INSULATION / VENTILATION

Attic Insulation:	•Loose Fiberglass/Mineral Wool in Main Attic
Roof Cavity Insulation:	•None Visible
Exterior Wall Insulation:	•Not Visible
Basement Wall Insulation:	•Fiberglass on Basement Walls
Vapor Retarders:	•Unknown
Roof Ventilation:	•Roof Vents •Soffit Vents
Exhaust Fan/vent Locations:	•Bathroom •Dryer

INSULATION / VENTILATION OBSERVATIONS

Positive Attributes

Insulation levels are typical for a home of this age and construction.

RECOMMENDATIONS / ENERGY SAVING SUGGESTIONS

Attic / Roof

- **Monitor:** While in the attic water stains were observed on the lower sections of the furnace flue. The insulation below the elbow also showed signs of past moisture. It appears that rain blew in under the rain cap and came down the interior of the flue until it got to the first joint where it then transferred to the outside surface and dripped off the elbow. This is a common condition in 80% of homes but very seldom is enough to penetrate completely through the insulation to the drywall below. Monitor for any additional wetness after rains.



LIMITATIONS OF INSULATION / VENTILATION INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Insulation/ventilation type and levels in concealed areas are not inspected. Insulation and vapor barriers are not disturbed and no destructive tests (such as cutting openings in walls to look for insulation) are performed.
- Potentially hazardous materials such as Asbestos and Urea Formaldehyde Foam Insulation (UFFI) cannot be positively identified without a detailed inspection and laboratory analysis. This is beyond the scope of the inspection.
- An analysis of indoor air quality is not part of our inspection unless explicitly contracted-for and discussed in this or a separate report.
- Any estimates of insulation R values or depths are rough average values.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Plumbing

DESCRIPTION OF PLUMBING

Water Supply Source:	•Public Water Supply
Service Pipe to House:	•Copper
Main Water Valve Location:	•Front Wall of Basement
Interior Supply Piping:	•Copper
Waste System:	•Public Sewer System
Drain, Waste, & Vent Piping:	•Plastic
Water Heater:	•Gas •Approximate Capacity (in gallons): 40 •Manufacturer: State •Serial Number: E00130823
Other Components:	•Sump Pump •Backflow Preventers on Hose Bibs

PLUMBING OBSERVATIONS

Positive Attributes

The plumbing system is in generally good condition. The water pressure supplied to the fixtures is average. Only a slight drop in flow was experienced when two fixtures were operated simultaneously. The plumbing fixtures appear to have been well-maintained.

General Comments

The plumbing system requires some typical minor improvements.

RECOMMENDATIONS / OBSERVATIONS

Water Heater

- **Monitor:** Water heaters have a typical life expectancy of 7 to 12 years. The existing unit is approaching or has exceeded this age range. One cannot predict with certainty when replacement will become necessary.

Plumbing Fixtures

- **Improve:** Cracked, deteriorated and/or missing master shower stall caulk should be replaced.
- **Improve:** Cracked, deteriorated and/or missing hall bath and master bath bathtub enclosure caulk could be improved.
- **Improve:** Cracked, deteriorated and/or missing master bath sink side splash caulk should be replaced.
Caulk has been repaired in Master bath and Hall Bath.
Caulk will be repaired in Master bath shower and sink side splash before closing.

LIMITATIONS OF PLUMBING INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Portions of the plumbing system concealed by finishes and/or storage (below sinks, etc.), below the structure, or beneath the ground surface are not inspected.
- Water quantity and water quality are not tested unless explicitly contracted-for and discussed in this or a separate report.
- Clothes washing machine connections are not inspected.
- Interiors of flues or chimneys which are not readily accessible are not inspected.
- Water conditioning systems, solar water heaters, fire and lawn sprinkler systems, and private waste disposal systems are not inspected unless explicitly contracted-for and discussed in this or a separate report.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Interior

DESCRIPTION OF INTERIOR

Wall And Ceiling Materials:	•Drywall
Floor Surfaces:	•Carpet •Tile •Vinyl/Resilient •Wood •Concrete
Window Type(s) & Glazing:	•Double/Single Hung •Fixed Pane •Thermal Pane
Doors:	•Wood-Hollow Core •Metal •Sliding Glass •Storm Door(s)

INTERIOR OBSERVATIONS

General Condition of Interior Finishes

On the whole, the interior finishes of the home are in above average condition. Typical minor flaws were observed in some areas.

General Condition of Windows and Doors

The majority of the doors and windows are good quality.

General Condition of Floors

The floors of the home are relatively level and walls are relatively plumb.

RECOMMENDATIONS / OBSERVATIONS

Wall / Ceiling Finishes

- **Monitor:** Water staining was noted at the basement ceiling.
- **Monitor:** Repaired drywall damage was noted (i.e. upper hall bath and master bath). Renovations were in progress at the time of the inspection.
- **Monitor:** Typical drywall flaws were observed that could include minor cracks, rough seams, nail popping, minor patching, etc. Any repairs would be discretionary. Overall condition is above average.

Floors

- **Monitor:** The vinyl flooring in the laundry room was observed to have minor stain.
- **Monitor:** The carpet shows typical wear and/or minor soiled spots and stains.

Windows

- **Monitor, Repair:** The interior window sills in the master bedroom is peeling. Repair is discretionary. **Repaired (sanded and repaied) 2/14/10**

Doors

- **Repair:** Doors should be trimmed or adjusted as necessary to work properly (i.e. master bath door). **Repaired 2/13/10**
- **Repair:** The threshold at the garage man door is damaged. Repair is needed.

Basement Leakage

- **Monitor:** No evidence of moisture penetration was visible in the basement at the time of the inspection. ***It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future.*** The vast majority of basement leakage problems are the result of insufficient control of storm water at the surface. The ground around the house should be sloped to encourage water to flow away from the foundation. Gutters and downspouts should act to collect roof water and drain the water at least five (5) feet from the foundation or into a functional storm sewer. Downspouts that are clogged or broken below grade level, or that discharge too close to the foundation are the most common source of basement leakage. Please refer to the Roofing and Exterior sections of the report for more information.

In the event that basement leakage problems are experienced, lot and roof drainage improvements should be undertaken as a first step. Please beware of contractors who recommend expensive solutions. Excavation, damp-proofing and/or the installation of drainage tiles should be a last resort. In some cases, however, it is necessary. Your plans for using the basement may also influence the approach taken to curing any dampness that is experienced. If another rain occurs before closing, it's recommended the basement be viewed again for any signs of moisture penetration.

LIMITATIONS OF INTERIOR INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions

- Furniture, storage, appliances and/or wall hangings are not moved to permit inspection and may block defects.
- Carpeting, window treatments, central vacuum systems, household appliances, recreational facilities, paint, wallpaper, and other finish treatments are not inspected.
- Recent renovations and/or interior painting concealed historical evidence.
- Portions of the foundation walls were concealed from view.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Appliances

DESCRIPTION OF APPLIANCES

Appliances Tested:	•Electric Range •Electric Cooktop •Microwave Oven •Dishwasher •Waste Disposer •Refrigerator
Laundry Facility:	•Dryer Vented to Building Exterior •Hot and Cold Water Supply for Washer
Other Components Tested:	•Waste Standpipe for Washer •Door Bell

APPLIANCES OBSERVATIONS

Positive Attributes

Most of the major appliances in the home are newer. All appliances that were tested responded satisfactorily. The kitchen and laundry facilities are well organized. The kitchen cabinetry is above average quality. The fixtures employed in the kitchen are high quality. The appliances that have been installed in the kitchen are good quality.

RECOMMENDATIONS / OBSERVATIONS

LIMITATIONS OF APPLIANCES INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions

- Thermostats, timers and other specialized features and controls are not tested.
- The temperature calibration, functionality of timers, effectiveness, efficiency and overall performance of appliances is outside the scope of this inspection.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Fireplaces / Wood Stoves

DESCRIPTION OF FIREPLACES / WOOD STOVES

Fireplaces: •Gas
Vents, Flues, Chimneys: •Metal Flue-Single Wall

FIREPLACES / WOOD STOVES OBSERVATIONS

Positive Attributes

On the whole, the fireplace and it's components are in above average condition.

RECOMMENDATIONS / OBSERVATIONS

LIMITATIONS OF FIREPLACES / WOOD STOVES INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions

- The interiors of flues or chimneys are not inspected.
- Firescreens, fireplace doors, appliance gaskets and seals, automatic fuel feed devices, mantles and fireplace surrounds, combustion make-up air devices, and heat distribution assists (gravity or fan-assisted) are not inspected.
- The inspection does not involve igniting or extinguishing fires nor the determination of draft.
- Fireplace inserts, stoves, or firebox contents are not moved.

Other Fireplace/Stove Components Not Inspected:

- Interiors of flues or chimneys

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.