



**Star
Home
Inspection Services**

Home Inspection Report

1302 Ann Ave Harrisonville, MO 64701

Inspection Date: 02/26/2010

Prepared For: Sarah Bloustine

Prepared By: Star Home Inspection Services LLC
705B SE Melody Lane, Suite 124
Lee's Summit, MO 64063
(816) 554-1110
(816) 554-2135 Fax

Report Number: 02262010-1A

Inspector: Alan DeMoss



Table Of Contents

REPORT OVERVIEW	3
STRUCTURE	7
ROOFING	8
EXTERIOR	10
ELECTRICAL	14
HEATING	16
COOLING / HEAT PUMPS	17
INSULATION / VENTILATION	18
PLUMBING	19
INTERIOR	20
APPLIANCES	22

Report Overview

THE HOUSE IN PERSPECTIVE

This is an average quality home. As with all homes, ongoing maintenance is required and improvements to the systems of the home will be needed over time. *The improvements that are recommended in this report are not considered unusual for a home of this age and location.* Please remember that there is no such thing as a perfect home.

CONVENTIONS USED IN THIS REPORT

For your convenience, the following conventions have been used in this report.

Major Concern: a system or component which is considered significantly deficient or is unsafe. Significant deficiencies need to be corrected and, except for some safety items, are likely to involve significant expense.

Safety Issue: denotes a condition that is unsafe and in need of prompt attention.

Repair: denotes a system or component which is missing or which needs corrective action to assure proper and reliable function.

Improve: denotes improvements which are recommended but not required.

Monitor: denotes a system or component needing further investigation and/or monitoring in order to determine if repairs are necessary.

Please note that those observations listed under “Discretionary Improvements” are not essential repairs, but represent logical long term improvements.

- For the purpose of this report, it is assumed that the house faces south.

IMPROVEMENT RECOMMENDATION HIGHLIGHTS / SUMMARY

The following is a synopsis of the potentially significant improvements that should be budgeted for over the short term. Other significant improvements, outside the scope of this inspection, may also be necessary. Please refer to the body of this report for further details on these and other recommendations.

All issues found in this report should be addressed with the appropriate parties to make any improvements, corrections or repairs necessary. All improvements, corrections and repairs should meet the satisfaction of the client named on this report and the inspection agreement associated with this report prior to closing. This report and the findings listed herein are intended for the client only and is not transferable without a signed written agreement.

Foundation

- **Monitor:** Common minor settlement cracks were observed in the foundation walls. This implies that some structural movement of the building has occurred. Cracks of this type should be watched for any sign of additional movement. In the absence of any sign of ongoing movement, repair should not be necessary.

Gutters & Downspouts

- **Repair:** The gutters require cleaning to avoid spilling roof runoff around the building – a potential source of water entry or water damage.
- **Repair:** The downspout(s) should discharge water at least five (5) feet from the house. Storm water should be encouraged to flow away from the building at the point of discharge.

Exterior Walls

- **Repair:** The loose siding should be re-secured to avoid water and/or wind damage (i.e. east side.)
- **Monitor, Repair:** Localized minor damage of the vinyl siding at the west side of the home was observed.

Exterior Eaves

- **Improve:** Cracked, deteriorated or missing caulk at the east side top eave aluminum covering should be improved.

Doors

- **Repair:** The paint on the door frame/ trims at the basement exterior and back exterior door is peeling and requires painting and caulking.
- **Repair:** Localized rot was visible on the basement exterior door trim/frame lower corner.
- **Repair:** The door window trim frame at the basement exterior door is damaged.

Garage

- **Repair, Safety Issue:** The east garage door opener did not automatically reverse under resistance to closing. ***There is a serious risk of injury, particularly to children, under this condition.*** Adjustment or replacement is needed if the opener has this feature.
- **Monitor:** The garage floor slab has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Lot Drainage

- **Repair:** The grading should be improved to promote the flow of storm water away from the house. This can often be accomplished by the addition of top soil. The ground should slope away from the house at a rate of one inch per foot for at least the first five feet. At least eight (8) inches of clearance should be maintained between soil level and the bottom of exterior wall siding. The void under the back steps should be filled. ***It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future.***
- **Monitor:** The driveway appears to slope slightly towards the house. This condition can cause water entry in the building. Unfortunately, it is difficult to improve this situation without adding a special intercept drain system at the garage entry. Monitor closely during heavy rains or water runoff. Improvements may be needed if the water does not drain off to the side of the driveway and away from the garage.

Deck

- **Monitor:** The support posts for the deck are below the soil. This configuration is prone to rot. Rising above soil level is recommended. The potential of rot could already be present.

Driveway

- **Monitor:** The driveway has settled and cracked. Persisting movement may result in the need for repairs.

Landscaping

- **Repair:** Tree branches should be trimmed away from the house to avoid damage to the building.
- **Repair:** Shrubs, bushes and/or vines growing on exterior walls need to be trimmed away from the structure to reduce the risk of water damage and insect infestation.

Fencing

- **Repair:** The gate at the west side of the home is missing.

Service / Entrance

- **Improve:** The service wires do not have adequate clearance from the ground. The top of the service mast and the service wires should be at least fifteen (15) feet from the ground.

Main Panel

- **Repair:** The ground fault circuit interrupter (GFCI) at the main panel did not respond properly to testing. It should be replaced.

Distribution Wiring

- **Repair:** Extension cords should not be used as permanent wiring. This wiring in the garage at garage door openers should be removed and replaced with permanent wiring and an outlet(s).

Outlets

- **Repair:** The east GFCI four gang outlet marked "ON" (Open Neutral) at the back fountain has an open neutral. This outlet and the circuit should be investigated and repaired as necessary.
- **Repair:** The back exterior fountain ground fault circuit interrupters (GFCI) outlets marked "FT" (failed test) did not respond correctly to testing during the inspection. These receptacle should be repaired or replaced.

Switches

- **Repair:** Missing switch cover plate in the main floor front southeast bedroom should be replaced to avoid a shock hazard.

Lights

- **Repair:** The light is inoperative (i.e. garage exterior, dining room, and northwest bedroom.) If the bulbs are not blown, the circuit should be repaired.

Furnace

- **Major Concern, Monitor:** Given the age of the furnace, it may be near the end of its useful life. You should reserve funds to be ready to purchase a new furnace.
- **Repair:** The humidifier is inoperative.

Return Air Ductwork

- **Repair:** Missing or damaged vent/return air register covers should be replaced.

Heat Pump/Air Conditioner

- **Monitor:** As is not uncommon for homes of this age and location, the heat pump/air conditioner is old. It may require a slightly higher level of maintenance, and may be more prone to major component breakdown. Predicting the frequency or time frame for repairs on any mechanical device is virtually impossible.
- **Repair:** Damaged insulation on refrigerant lines should be repaired.
- **Monitor:** The fins of the outdoor portion of the heat pump/air conditioner were observed to be damaged. This condition can reduce the efficiency of the system.

Plumbing Fixtures

- **Repair:** The hall bath tub faucet is leaky
- **Repair:** The hall bath shower head is leaky at the hinge connection when turned on.
- **Improve:** Cracked, deteriorated and/or missing kitchen sink back splash caulk could be improved.

Oven

- **Repair:** The oven light is inoperative.

Door Bell

- **Repair:** The door bell is inoperative.

Wall / Ceiling Finishes

- **Monitor:** Water staining was noted at the garage ceiling.
- **Repair:** Damage to the garage ceiling was observed.
- **Monitor:** Typical drywall flaws were observed that could include minor cracks, rough seams, nail popping, minor patching, etc. Any repairs would be discretionary.
- **Improve:** Damage to the attic hatch cover was observed.

Floors

- **Monitor:** The basement carpet shows typical wear and/or soiled spots and stains.
- **Repair:** The installation of the trim is incomplete at the basement bath, front entry and kitchen.

Windows

- **Monitor:** It may be desirable to replace the basement window screen where missing. The owner should be consulted regarding any screens that may be in storage.

Doors

- **Monitor, Repair:** Pet damage was noted on the garage man door frame/trim.
- **Repair:** The screen for the back storm door is damaged.

Basement Leakage

- **Monitor:** No evidence of moisture penetration was visible in the basement at the time of the inspection. *It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future.* The vast majority of basement leakage problems are the result of insufficient control of storm water at the surface. The ground around the house should be sloped to encourage water to flow away from the foundation. Gutters and downspouts should act to collect roof water and drain the water at least five (5) feet from the foundation or into a functional storm sewer. Downspouts that are clogged or broken below grade level, or that discharge too close to the foundation are the most common source of basement leakage. Please refer to the Roofing and Exterior sections of the report for more information.

In the event that basement leakage problems are experienced, lot and roof drainage improvements should be undertaken as a first step. Please beware of contractors who recommend expensive solutions. Excavation, damp-proofing and/or the installation of drainage tiles should be a last resort. In some cases, however, it is necessary. Your plans for using the basement may also influence the approach taken to curing any dampness that is experienced. If another rain occurs before closing, it's recommended the basement be viewed again for any signs of moisture penetration.

THE SCOPE OF THE INSPECTION

All components designated for inspection in the ASHI® Standards of Practice are inspected, except as may be noted in the "Limitations of Inspection" sections within this report.

It is the goal of the inspection to put a home buyer in a better position to make a buying decision. Not all improvements will be identified during this inspection. Unexpected repairs should still be anticipated. The inspection should not be considered a guarantee or warranty of any kind.

This inspection is visual only. A representative sample of building components are viewed in areas that are accessible at the time of the inspection. No destructive testing or dismantling of building components is performed.

Please refer to the pre-inspection contract for a full explanation of the scope of the inspection.

WEATHER CONDITIONS

Dry weather conditions prevailed at the time of the inspection.

The estimated outside temperature was 25 degrees F.

RECENT WEATHER CONDITIONS

Winter weather conditions have been experienced in the days leading up to the inspection.

Structure

DESCRIPTION OF STRUCTURE

Foundation:	•Poured Concrete •Basement Configuration •90% Of Foundation Was Not Visible From Inside Due To Finished Walls and/or Storage
Columns:	•Steel
Floor Structure:	•Wood Joist •Concrete
Wall Structure:	•Wood Frame
Ceiling Structure:	•Joist
Roof Structure:	•Rafters •Plywood Sheathing

STRUCTURE OBSERVATIONS

Positive Attributes

The construction of the home is good quality. The materials and workmanship, where visible, are good. The visible joist spans appear to be within typical construction practices. The inspection did not discover evidence of substantial structural movement.

General Comments

No major defects were observed in the accessible structural components of the house.

RECOMMENDATIONS / OBSERVATIONS

Foundation

- **Monitor:** Common minor settlement cracks were observed in the foundation walls. This implies that some structural movement of the building has occurred. Cracks of this type should be watched for any sign of additional movement. In the absence of any sign of ongoing movement, repair should not be necessary.

LIMITATIONS OF STRUCTURE INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Structural components concealed behind finished surfaces could not be inspected.
- Only a representative sampling of visible structural components were inspected.
- Furniture and/or storage restricted access to some structural components.
- Engineering or architectural services such as calculation of structural capacities, adequacy, or integrity are not part of a home inspection.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Roofing

DESCRIPTION OF ROOFING

Roof Covering:	•Asphalt Shingle
Roof Flashings:	•Roofing Material (Shingles)
Chimneys:	•None
Roof Drainage System:	•Aluminum •Downspouts discharge above grade
Skylights:	•None
Method of Inspection:	•Walked on roof

ROOFING OBSERVATIONS

Positive Attributes

The roof coverings are to be in generally good condition. During re-roofing, it appears that the old roofing materials were removed before the installation of the existing roofing materials. Where investigated, eave protection has been installed below the sloped roof coverings. This reduces the risk of roof leakage, should ice damming develop in the winter. The installation of the roofing materials has been performed in a professional manner. The quality of the installation is above average. Better than average quality materials have been employed as roof coverings. Roof flashing details appear to be in good order.

RECOMMENDATIONS / OBSERVATIONS

Gutters & Downspouts

- **Repair:** The gutters require cleaning to avoid spilling roof runoff around the building – a potential source of water entry or water damage.



- **Repair:** The downspout(s) should discharge water at least five (5) feet from the house. Storm water should be encouraged to flow away from the building at the point of discharge.



LIMITATIONS OF ROOFING INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Not all of the underside of the roof sheathing is inspected for evidence of leaks.
- Evidence of prior leaks may be disguised by interior finishes.
- Estimates of remaining roof life are approximations only and do not preclude the possibility of leakage. Leakage can develop at any time and may depend on rain intensity, wind direction, ice build up, and other factors.
- Antennae, chimney/flue interiors which are not readily accessible are not inspected and could require repair.
- Roof inspection may be limited by access, condition, weather, or other safety concerns.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Exterior

DESCRIPTION OF EXTERIOR

Wall Covering:	•Vinyl Siding
Eaves, Soffits, And Fascias:	•Aluminum
Exterior Doors:	•Metal
Window/Door Frames and Trim:	•Vinyl-Covered •Metal
Entry Driveways:	•Concrete
Entry Walkways And Patios:	•Concrete
Porches, Decks, Steps, Railings:	•Concrete •Treated Wood •Plastic Front Steps Railing
Overhead Garage Door(s):	•Plastic •Automatic Opener Installed
Surface Drainage:	•Level Grade •Graded Away From House •Graded Towards House
Retaining Walls:	•Prefab Masonry
Fencing:	•Chain Link

EXTERIOR OBSERVATIONS

Positive Attributes

The exterior siding that has been installed on the house is relatively low maintenance. Window frames are clad, for the most part, with a low maintenance material. The aluminum soffits and fascia are a low-maintenance feature of the exterior of the home. The garage completely finished. Freeze resistant hose bibs (exterior faucets) have been installed.

General Comments

The exterior of the home is generally in good condition.

RECOMMENDATIONS / OBSERVATIONS

Exterior Walls

- **Repair:** The loose siding should be re-secured to avoid water and/or wind damage (i.e. east side.)



- **Monitor, Repair:** Localized minor damage of the vinyl siding at the west side of the home was observed.



Exterior Eaves

- **Improve:** Cracked, deteriorated or missing caulk at the east side top eave aluminum covering should be improved.



View from east roof ridge

Doors

- **Repair:** The paint on the door frame/ trims at the basement exterior and back exterior door is peeling and requires painting and caulking.
- **Repair:** Localized rot was visible on the basement exterior door trim/frame lower corner.
- **Repair:** The door window trim frame at the basement exterior door is damaged.

Garage

- **Repair, Safety Issue:** The east garage door opener did not automatically reverse under resistance to closing. ***There is a serious risk of injury, particularly to children, under this condition.*** Adjustment or replacement is needed if the opener has this feature.
- **Monitor:** The garage floor slab has typical cracks usually the result of shrinkage and/or settling of the slab as it cures. Shrinkage cracks are very common and are not normally a concern.

Lot Drainage

- **Repair:** The grading should be improved to promote the flow of storm water away from the house. This can often be accomplished by the addition of top soil. The ground should slope away from the house at a rate of one inch per foot for at least the first five feet. At least eight (8) inches of clearance should be maintained between soil level and the bottom of exterior wall siding. The void under the back steps should be filled. *It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future.*



- **Monitor:** The driveway appears to slope slightly towards the house. This condition can cause water entry in the building. Unfortunately, it is difficult to improve this situation without adding a special intercept drain system at the garage entry. Monitor closely during heavy rains or water runoff. Improvements may be needed if the water does not drain off to the side of the driveway and away from the garage.

Deck

- **Monitor:** The support posts for the deck are below the soil. This configuration is prone to rot. Raising above soil level is recommended. The potential of rot could already be present.

Driveway

- **Monitor:** The driveway has settled and cracked. Persisting movement may result in the need for repairs.

Landscaping

- **Repair:** Tree branches should be trimmed away from the house to avoid damage to the building.
- **Repair:** Shrubs, bushes and/or vines growing on exterior walls need to be trimmed away from the structure to reduce the risk of water damage and insect infestation.



Fencing

- **Repair:** The gate at the west side of the home is missing.

LIMITATIONS OF EXTERIOR INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- A representative sample of exterior components was inspected rather than every occurrence of components.
- The inspection does not include an assessment of geological, geotechnical, or hydrological conditions, or environmental hazards.
- Screening, shutters, awnings, or similar seasonal accessories, fences, recreational facilities, outbuildings, seawalls, break-walls, docks, erosion control and earth stabilization measures are not inspected unless specifically agreed-upon and documented in this report.
- Storage in the garage restricted the inspection.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Electrical

DESCRIPTION OF ELECTRICAL

Size of Electrical Service:	•120/240 Volt Main Service - Service Size: 200 Amps
Service Drop:	•Overhead
Service Entrance Conductors:	•Copper
Service Equipment & Main Disconnects:	•Main Service Rating 200 Amps •Breakers •Located: Garage
Service Grounding:	•Copper •Ground Rod Connection
Service Panel & Overcurrent Protection:	•Panel Rating: 200 Amp •Breakers •Located: Garage
Sub-Panel(s):	•None Visible
Distribution Wiring:	•Copper
Wiring Method:	• Non-Metallic Cable "Romex"
Switches & Receptacles:	•Grounded and Ungrounded
Ground Fault Circuit Interrupters:	•Exterior
Smoke Detectors:	•Present

ELECTRICAL OBSERVATIONS

Positive Attributes

The size of the electrical service is sufficient for typical single family needs. The electrical panel is well arranged and all fuses/breakers are properly sized relative to the wiring. Generally speaking, the electrical system is in good order. Dedicated 220 volt circuits have been provided for all 220 volt appliances within the home. All visible wiring within the home is copper. This is a good quality electrical conductor.

General Comments

Inspection of the electrical system revealed the need for typical, minor repairs. Although these are not costly to repair, they should be high priority for safety reasons. *Unsafe electrical conditions represent a shock hazard.* A licensed electrician should be consulted to undertake the repairs recommended below.


RECOMMENDATIONS / OBSERVATIONS

Service / Entrance

- **Improve:** The service wires do not have adequate clearance from the ground. The top of the service mast and the service wires should be at least fifteen (15) feet from the ground.

Main Panel

- **Repair:** The ground fault circuit interrupter (GFCI) at the main panel did not respond properly to testing. It should be replaced.



Distribution Wiring

- **Repair:** Extension cords should not be used as permanent wiring. This wiring in the garage at garage door openers should be removed and replaced with permanent wiring and an outlet(s).

Outlets

- **Repair:** The east GFCI four gang outlet marked "ON" (Open Neutral) at the back fountain has an open neutral. This outlet and the circuit should be investigated and repaired as necessary.
- **Repair:** The back exterior fountain ground fault circuit interrupters (GFCI) outlets marked "FT" (failed test) did not respond correctly to testing during the inspection. These receptacle should be repaired or replaced.

Switches

- **Repair:** Missing switch cover plate in the main floor front southeast bedroom should be replaced to avoid a shock hazard.

Lights

- **Repair:** The light is inoperative (i.e. garage exterior, dining room, and northwest bedroom.) If the bulbs are not blown, the circuit should be repaired.

Discretionary Improvements

The installation of ground fault circuit interrupter (GFCI) devices is advisable on exterior, garage, bathroom and some kitchen outlets. Any whirlpool or swimming pool equipment should also be fitted with GFCI's as they offer protection from shock or electrocution.

LIMITATIONS OF ELECTRICAL INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Electrical components concealed behind finished surfaces are not inspected.
- Only a representative sampling of outlets and light fixtures were tested.
- Furniture and/or storage restricted access to some electrical components which may not be inspected.
- The inspection does not include remote control devices, alarm systems and components, low voltage wiring, systems, and components, ancillary wiring, systems, and other components which are not part of the primary electrical power distribution system.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Heating

DESCRIPTION OF HEATING

Energy Source:	•Electricity
Heating System Type:	•Forced Air Furnace •Manufacturer: Carrier •Serial Number: E8A91190
Heat Distribution Methods:	•Ductwork
Other Components:	•Humidifier

HEATING OBSERVATIONS

Positive Attributes

Adequate heating capacity is provided by the system. Heat distribution within the home is adequate. The heating system is controlled by a “set back” thermostat. This type of thermostat, if set up correctly, helps reduce heating costs.

General Comments

The heating system is old and may be approaching the end of its life.

RECOMMENDATIONS / OBSERVATIONS

Furnace

- **Major Concern, Monitor:** Given the age of the furnace, it may be near the end of its useful life. You should reserve funds to be ready to purchase a new furnace.
- **Repair:** The humidifier is inoperative.

Return Air Ductwork

- **Repair:** Missing or damaged vent/return air register covers should be replaced.



LIMITATIONS OF HEATING INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- The adequacy of heat supply or distribution balance is not inspected.
- The interior of flues or chimneys which are not readily accessible are not inspected.
- The furnace heat exchanger, humidifier, or dehumidifier, and electronic air filters are not inspected.
- Solar space heating equipment/systems are not inspected.
- The programmable thermostat was not tested.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Cooling / Heat Pumps

DESCRIPTION OF COOLING / HEAT PUMPS

Energy Source:	•Electricity
Central System Type:	•Air Conditioner/Heat Pump System •Manufacturer: Carrier
	•Serial Number: C854694
Size of Circuit:	•Breaker Size In Main Panel: 30 Amps

COOLING / HEAT PUMPS OBSERVATIONS

Positive Attributes

The capacity and configuration of the system should be sufficient for the home. The heat pump serves to air-condition the home and provide heat during cooler weather conditions. The location of the return air vents is well suited to air conditioning.

General Comments

As the system is old, it will require repairs or replacement soon.

RECOMMENDATIONS / OBSERVATIONS

Heat Pump/Air Conditioner

- **Monitor:** As is not uncommon for homes of this age and location, the heat pump/air conditioner is old. It may require a slightly higher level of maintenance, and may be more prone to major component breakdown. Predicting the frequency or time frame for repairs on any mechanical device is virtually impossible.
- **Repair:** Damaged insulation on refrigerant lines should be repaired.
- **Monitor:** The fins of the outdoor portion of the heat pump/air conditioner were observed to be damaged. This condition can reduce the efficiency of the system.

LIMITATIONS OF COOLING / HEAT PUMPS INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Window mounted air conditioning units are not inspected.
- The cooling supply adequacy or distribution balance are not inspected.
- **The heat pump/air conditioning system could not be tested as the outdoor temperature was below 60 degrees F.**

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Insulation / Ventilation

DESCRIPTION OF INSULATION / VENTILATION

Attic Insulation:	•Loose Fiberglass/Mineral Wool in Main Attic
Roof Cavity Insulation:	•None Visible
Exterior Wall Insulation:	•Not Visible
Basement Wall Insulation:	•Not Visible
Vapor Retarders:	•Unknown
Roof Ventilation:	•Roof Vents •Soffit Vents •Gable Vents
Exhaust Fan/vent Locations:	•Bathroom •Dryer

INSULATION / VENTILATION OBSERVATIONS

Positive Attributes

Insulation levels are typical for a home of this age and construction.

RECOMMENDATIONS / ENERGY SAVING SUGGESTIONS

LIMITATIONS OF INSULATION / VENTILATION INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Insulation/ventilation type and levels in concealed areas are not inspected. Insulation and vapor barriers are not disturbed and no destructive tests (such as cutting openings in walls to look for insulation) are performed.
- Potentially hazardous materials such as Asbestos and Urea Formaldehyde Foam Insulation (UFFI) cannot be positively identified without a detailed inspection and laboratory analysis. This is beyond the scope of the inspection.
- An analysis of indoor air quality is not part of our inspection unless explicitly contracted-for and discussed in this or a separate report.
- Any estimates of insulation R values or depths are rough average values.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Plumbing

DESCRIPTION OF PLUMBING

Water Supply Source:	•Public Water Supply
Service Pipe to House:	•Copper
Main Water Valve Location:	•Side Wall of Basement
Interior Supply Piping:	•Copper
Waste System:	•Public Sewer System
Drain, Waste, & Vent Piping:	•Plastic •Not Visible
Water Heater:	•Electric •Approximate Capacity (in gallons): 50 •Manufacturer: Bradford White •Serial Number: ZC2944652
Other Components:	•Backflow Preventers on Hose Bibs

PLUMBING OBSERVATIONS

Positive Attributes

The plumbing system is in generally good condition. The piping system within the home, for both supply and waste, is a good quality system. The water pressure supplied to the fixtures is above average. Only a slight drop in flow was experienced when two fixtures were operated simultaneously. Some of the plumbing fixtures within the home have been upgraded. The plumbing fixtures appear to have been well-maintained.

General Comments

The plumbing system requires some typical minor improvements.

RECOMMENDATIONS / OBSERVATIONS

Plumbing Fixtures

- **Repair:** The hall bath tub faucet is leaky
- **Repair:** The hall bath shower head is leaky at the hinge connection when turned on.
- **Improve:** Cracked, deteriorated and/or missing kitchen sink back splash caulk could be improved.

LIMITATIONS OF PLUMBING INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions:

- Portions of the plumbing system concealed by finishes and/or storage (below sinks, etc.), below the structure, or beneath the ground surface are not inspected.
- Water quantity and water quality are not tested unless explicitly contracted-for and discussed in this or a separate report.
- Clothes washing machine connections are not inspected.
- Interiors of flues or chimneys which are not readily accessible are not inspected.
- Water conditioning systems, solar water heaters, fire and lawn sprinkler systems, and private waste disposal systems are not inspected unless explicitly contracted-for and discussed in this or a separate report.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Interior

DESCRIPTION OF INTERIOR

Wall And Ceiling Materials:	•Drywall •Paneling
Floor Surfaces:	•Carpet •Tile •Vinyl/Resilient •Concrete
Window Type(s) & Glazing:	•Double/Single Hung •Sliders •Thermal Pane •Single Pane (Basement)
Doors:	•Wood-Hollow Core •Metal •Storm Door(s)

INTERIOR OBSERVATIONS

General Condition of Interior Finishes

On the whole, the interior finishes of the home are in average condition. Typical flaws were observed in some areas.

General Condition of Windows and Doors

The majority of the doors and windows are good quality.

General Condition of Floors

The floors of the home are relatively level and walls are relatively plumb.

RECOMMENDATIONS / OBSERVATIONS

Wall / Ceiling Finishes

- **Monitor:** Water staining was noted at the garage ceiling.
- **Repair:** Damage to the garage ceiling was observed.
- **Monitor:** Typical drywall flaws were observed that could include minor cracks, rough seams, nail popping, minor patching, etc. Any repairs would be discretionary.
- **Improve:** Damage to the attic hatch cover was observed.

Floors

- **Monitor:** The basement carpet shows typical wear and/or soiled spots and stains.
- **Repair:** The installation of the trim is incomplete at the basement bath, front entry and kitchen.

Windows

- **Monitor:** It may be desirable to replace the basement window screen where missing. The owner should be consulted regarding any screens that may be in storage.

Doors

- **Monitor, Repair:** Pet damage was noted on the garage man door frame/trim.
- **Repair:** The screen for the back storm door is damaged.

Basement Leakage

- **Monitor:** No evidence of moisture penetration was visible in the basement at the time of the inspection. ***It should be understood that it is impossible to predict whether moisture penetration will pose a problem in the future.*** The vast majority of basement leakage problems are the result of insufficient control of storm water at the surface. The ground around the house should be sloped to encourage water to flow away from the foundation. Gutters and downspouts should act to collect roof water and drain the water at least five (5) feet from the foundation or into a functional storm sewer. Downspouts that are clogged or broken below grade level, or that discharge too close to the foundation are the most common source of basement leakage. Please refer to the Roofing and Exterior sections of the report for more information.

In the event that basement leakage problems are experienced, lot and roof drainage improvements should be undertaken as a first step. Please beware of contractors who recommend expensive solutions. Excavation, damp-proofing and/or the installation of drainage tiles should be a last resort. In some cases, however, it is necessary. Your plans for using the basement may also influence the approach taken to curing any dampness that is experienced. If another rain occurs before closing, it's recommended the basement be viewed again for any signs of moisture penetration.

LIMITATIONS OF INTERIOR INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions

- Furniture, storage, appliances and/or wall hangings are not moved to permit inspection and may block defects.
- Carpeting, window treatments, central vacuum systems, household appliances, recreational facilities, paint, wallpaper, and other finish treatments are not inspected.
- Portions of the foundation walls were concealed from view.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.

Appliances

DESCRIPTION OF APPLIANCES

Appliances Tested:	•Electric Range •Electric Cooktop •Microwave Oven •Dishwasher
Laundry Facility:	•Waste Disposer •Refrigerator
Other Components Tested:	•Dryer Vented to Building Exterior •Hot and Cold Water Supply for Washer •Waste Standpipe for Washer •Door Bell

APPLIANCES OBSERVATIONS

Positive Attributes

Most appliances that were tested responded satisfactorily. The kitchen and laundry facilities are well organized. The fixtures employed in the kitchen are high quality.

General Comments

Only minor improvements to the appliances are needed.

RECOMMENDATIONS / OBSERVATIONS

Oven

- **Repair:** The oven light is inoperative.

Door Bell

- **Repair:** The door bell is inoperative.

LIMITATIONS OF APPLIANCES INSPECTION

As we have discussed and as described in your inspection contract, this is a visual inspection limited in scope by (but not restricted to) the following conditions

- Thermostats, timers and other specialized features and controls are not tested.
- The temperature calibration, functionality of timers, effectiveness, efficiency and overall performance of appliances is outside the scope of this inspection.

Please also refer to the pre-inspection contract for a detailed explanation of the scope of this inspection.